The Home Shop Machinist

1996 Volume Twelve Index

January/February – J/F
March/April – M/A
May/June – M/J
July/August – J/A
September/October – S/O
November/December – N/D

A

ACKER, STEVE
Cutting Steel with a Circular Saw Blade S/O 33
Hot Bluing Steel S/O 28
Adapting the Sherline for Wheel Cutting and Pinion Making (see SMITH, W. R.)
Almost a Product Review S/O 23
Atlas Tailstock Modification N/D 55

B

BENJAMIN, JOHN
Product Review J/A 22
Bit of Inspiration, A J/A 24
BLACKMON, BILLY J.
Internal Spindle Stop J/A 46
BLOCKER, DAVID C.
Chips & Sparks
Milling a Flat S/O 21
No More Shocks M/A 19
BOCHERT, JOHN
Proper Use of Diamond Dressers, The J/A 56
Book Review
Designing Cost-Efficient Mechanisms J/A 23
BOOTH, KATHY
Guest Editorial M/J 4
BOWER, EARL L.
Indicator Stand, An J/A 48
BROWN, CHARLES
Chips & Sparks
Holding Small Threading Dies N/D 20
Building Phil Duclos' Model Maker's Dividing Head M/J 46
BURKE, DESMOND
How and Why of Tangential Cutting, The M/J 28

C

Carbide Inserts J/A 58
Chips & Sparks
Advantage of Three-phase M/A 19
Change Gears S/O 63
Hacksaw Cuts Simplified M/A 19
Holding Small Threading Dies N/D 20
Lathe Handles J/A 21
Long Story Shortened J/A 20
Machine Mobility S/O 20
Made in the Shade S/O 21
Magnetic Base Indicator Mount S/O 22
Mill/drill Tips J/F 21
Milling a Flat S/O 21
No More Shocks M/A 19
Setting Up Work in the Lathe S/O 33
Substitute Tailstock Center M/A 19
Three-phase Idler Flywheel J/A 20
Tighten the Spindle Pulley S/O 22
Working in the Dark J/A 67
Cleaning a Universal Chuck J/F 57
COLLINS, MARSH
Building Phil Duclos' Model Maker's Dividing Head M/J 46
CRUNKLETON, JOHN
Bit of Inspiration, A
Work of John Crunkleton, The J/A 24
Cutting Steel with a Circular Saw Blade S/O 33
Cylinders and Pistons for Two-stroke Cycle Model Engines N/D 38

D

DAVIS, M. O.
Chips & Sparks
Magnetic Base Indicator Mount S/O 22
DOLLNIG, WERNER W.
Chips & Sparks
Working in the Dark J/A 67
DOWLING, THOMAS W. III
Engineering Plastics J/F 33
DUCLOS, PHILIP
Maverick Engine
Part 3 J/F 44
Part 4 M/A 42

E

EISLER, DAVID
Chips & Sparks
Mill/drill Tips J/F 21
Electrical Discharge Machining – Removing Metal By Spark Erosion (see LANGLOIS, ROBERT P.)
Elevated or Auxiliary Lathe Spindle, An (see McLEAN, FRANK A.)
Engineering Plastics J/F 33
EYER, CHARLES
Variable Speed DC Motor for the Home Shop M/J 50

F

Fixturing With Collets M/J 60
FRENCH, DICK
Chips & Sparks
Advantage of Three-phase M/A 19
From the Editor (see RICE, JOE)
From the Scrapbox (see McLEAN, FRANK A.)

G

GASCOYNE, JOHN B.
Get a Handle On Your Lathe N/D 46
GENEVRO, GEORGE
Cylinders and Pistons for Two-stroke Cycle Model Engines N/D 38
Get a Handle On Your Lathe N/D 46
GRAHAM, DOUGLAS
Rebirth of a Model C South Bend Lathe, The N/D 49
Gunsmith's Workbench, A – German Silver Escutcheons J/A 52

H

HABICHER, WOLFGANG F.
Small Shop Butt Welder, A M/A 48
HOBBY PROJECTS
Building Phil Duclos' Model Maker's Dividing Head M/J 46
Cylinders and Pistons for Two-stroke Cycle Model Engines N/D 38
Gunsmith's Workbench, A – German Silver Escutcheons J/A 52
Maverick Engine (see DUCLOS, PHILIP)
Steam/Air Engine for Fun, A S/O 48
Stirling-powered Tractor, A (see KOUHOUPT, RUDY)
Variations on a "Whatzit" N/D 48
Walking Staff, The S/O 43
HOFFMAN, EDWARD G.
Jigs & Fixtures
Fixturing With Collets
Part 1 M/J 60
Part 2 J/A 60
Part 3 N/D 62
Locating Pins
Part 2 J/F 62
Part 3 M/A 54
Lathe Tips J/F 50
Product Review J/F 23
HOLLENBECK, KEN
Variations on a "Whatzit" N/D 48
Hot Bluing Steel S/O 28
HOUSEMAN, ROBIN
Three-phase Idler Flywheel J/A 20
How and Why of Tangential Cutting, The M/J 28
How to Make a Chuck Backplate S/O 52
How to Set Up and Use a Drill Grinding Attachment M/A 57

I

Indicator Stand, An J/A 48
Internal Spindle Stop J/A 46
ISAAC, P.
Chips & Sparks
Change Gears S/O 63

J

Jigs & Fixtures (see HOFFMAN, EDWARD G.)
JOHNSON, D. E.
Mill-drill Adventures
Part 5 **Power Feed for the Main Table and a Rotary Table, A** J/F 26
Part 6 **Power Feed for the Main Table and a Rotary Table, A** continued M/A 32
Part 7 **Keeping Track of the Cutting Tool and Table Positions** J/A 30
JOLY, DAVID
Book Review J/A 23
JONES, BRUCE
Atlas Tailstock Modification N/D 55

K

KEREKGYARTO, GEORGE
Steam/Air Engine for Fun, A S/O 48
KOUHOUPT, RUDY
Micro Machinist, The
Little Job Cement Mixer
Part 1 J/F 54
Part 2 M/A 50
Part 3 M/J 55
Part 4 J/A 51
Make Your Own Lathe Collets
Part 1 S/O 58
Part 2 N/D 56

Stirling-powered Tractor, A
Part 1 N/D 24
Using the Diamond Toolholder M/J 24
KRATT, HENRY J.
Stuck Chucks, One-more-time, Didactic #17 J/A 49

L
LaMANCE, THOMAS
Chips & Sparks
Substitute Tailstock Center M/A 19
LANGLOIS, ROBERT P.
Electrical Discharge Machining – Removing Metal By Spark Erosion
Part 5 Head and EDM Operation, The J/F 34
Part 6 Other Odds and Ends M/A 37
LATHE ACCESSORIES
Cleaning a Universal Chuck J/F 57
Elevated or Auxiliary Lathe Spindle, An
(see McLEAN, FRANK A.)
Get a Handle On Your Lathe N/D 46
How to Make a Chuck Backplate S/O 52
Indicator Stand, An J/A 48
Internal Spindle Stop J/A 46
Pseudo Drawbar for the Tailstock, A N/D 52
Quick-release T-rest for the Sherline Lathe, A J/A 36
Taig Lathe Tool Rest, A J/A 54
Trepanning Tool, A M/J 58
Lathe Tips J/F 50
LAUTARD, GUY
Product Review M/A 20
Video Reviews M/J 20
LINDQUIST, DAVID
Product Review J/F 22
Little Job Cement Mixer
(see KOUHOUPT, RUDY)
Locating Pins
(see HOFFMAN, EDWARD G.)

M
Machining on the Internet S/O 62
MADISON, JAMES
Table Stop J/A 44
Make Your Own Lathe Collets
(see KOUHOUPT, RUDY)
Maverick Engine
(see DUCLOS, PHILIP)
McKINLEY, CLOVER
From the Editors S/O 4
McLEAN, FRANK A.
Elevated or Auxiliary Lathe Spindle, An
Part 1 S/O 34
Part 2 N/D 32
From the Scrapbox
Cleaning a Universal Chuck J/F 57
How to Make a Chuck Backplate S/O 52
How to Set Up and Use a Drill Grinding Attachment M/A 57
Spur Center for Turning Wood, A N/D 59
Taig Lathe Tool Rest, A J/A 54
Trepanning Tool, A M/J 58
Time for Reflection, A S/O 56
MENDUM, J. H.
Machining on the Internet S/O 62
Micro Machinist, The
(see KOUHOUPT, RUDY)
Mill-drill Adventures
(see JOHNSON, D. E.)
MILLING ACCESSORIES
Mill-drill Adventures
(see JOHNSON, D. E.)
Remote Switch for the Mill M/J 49
Table Stop J/A 44
MORROW, LAURIE
Gunsmith's Workbench, A
German Silver Escutcheons J/A 52

N
NETZEL, WALT
Sharpening Tungsten Carbide Drills J/A 50
NOLAN, PETE
Almost a Product Review S/O 23
NYMAN, PHIL
Pseudo Drawbar for the Tailstock, A N/D 52

P
Product Review
Almost a Product Review S/O 23
Emco Maier D1-4" Cam Lock Fixture Plate J/F 22
FlexArm System J/F 23
Ornamental Turning Lathe M/A 20
Takang Model 1760G Lathe J/A 22
Proper Use of Diamond Dressers, The J/A 56
Pseudo Drawbar for the Tailstock, A N/D 52

Q
Quick-release T-rest for the Sherline Lathe, A J/A 36

R
RACHUNAS, ART
Chips & Sparks
Tighten the Spindle Pulley S/O 22
RAUBACH, PIERCE
Lathe Handles J/A 21
Rebirth of a Model C South Bend Lathe, The N/D 49
Remote Switch for the Mill M/J 49
RICE, JOE
From the Editor J/F 2, M/A 4, J/A 4, S/O 4, N/D 4

S
Sharpening Tungsten Carbide Drills J/A 50
SHOP IMPROVEMENT PROJECTS
Electrical Discharge Machining – Removing Metal By Spark Erosion M/A 37
(see LANGLOIS, ROBERT P.)
How to Set Up and Use a Drill Grinding Attachment M/A 57
Sliding Bevel Gage with Protractor, A M/J 31
Small Shop Butt Welder, A M/A 48
Variable Speed DC Motor for the Home Shop M/J 50
Sliding Bevel Gage with Protractor, A M/J 31
Small Shop Butt Welder, A M/A 48
SMITH, W. R.
Adapting the Sherline for Wheel Cutting and Pinion Making
Part 1 M/A 24
Part 2 M/J 36
Quick-release T-rest for the Sherline Lathe, A J/A 36
Spur Center for Turning Wood, A N/D 59
STANAITIS, PETE
Chips & Sparks
Made in the Shade S/O 21
Steam/Air Engine for Fun, A S/O 48
Stirling-powered Tractor, A
(see KOUHOUPT, RUDY)
STONE, EDWARD P.
Lathe Tips J/F 50
Stuck Chucks, One-more-time, Didactic #17 J/A 49
Taig Lathe Tool Rest, A J/A 54

T
Table Stop J/A 44
TECHNIQUES
Adapting the Sherline for Wheel Cutting and Pinion Making M/A 24
(see SMITH, W. R.)
Atlas Tailstock Modification N/D 55
Carbide Inserts J/A 58
Cutting Steel with a Circular Saw Blade S/O 33
Engineering Plastics J/F 33
Hot Bluing Steel S/O 28
How and Why of Tangential Cutting, The M/J 28
Lathe Tips J/F 50
Proper Use of Diamond Dressers, The J/A 56
Rebirth of a Model C South Bend Lathe, The N/D 49
Sharpening Tungsten Carbide Drills J/A 50
Stuck Chucks, One-more-time, Didactic #17 J/A 49
Using the Diamond Toolholder M/J 24
Time for Reflection, A S/O 56
TITUS, DON
Walking Staff, The S/O 43
Trepanning Tool, A M/J 58

U
Using the Diamond Toolholder M/J 24

V
Variable Speed DC Motor for the Home Shop M/J 50
Variations on a "Whatzit" N/D 48
Video Review
"American's View of the English Wheel, An" M/J 20
"Bedding, Scoping, and Crowning the Remington 700" M/J 20
"Correcting Bolt Lug Engagement and Excess Headspace" M/J 20
"Edge those Panels" M/J 20
"Truing Your Action and Installing a New Barrel" M/J 20
VORDAHL, NORMAN A.
Chips & Sparks
Machine Mobility S/O 20
VOSS, C. O.
Remote Switch for the Mill M/J 49

W
Walking Staff, The S/O 43
WHIPPLE, STEVEN G.
Chips & Sparks
Long Story Shortened J/A 20
WILDER, FRED E.
Chips & Sparks
Hacksaw Cuts Simplified M/A 19
WILLOX, PETER J.
Chips & Sparks
Setting Up Work in the Lathe S/O 33
WITHEROW, JEFF
Carbide Inserts J/A 58
WRIGHT, TED
Sliding Bevel Gage with Protractor, A M/J 31